# Work Order ID 61814



Page 1

Tuesday, Septem	ber 07, 2010	12:43:57 PM									
tem ID: Revision ID:	D4103-1		·	Accept			s	etup Star	t		
	Step / Handle			e T				Stóp			
Start Date: Required Date: Reference:	9/7/2010 10/13/2010	Start Qty: 8.00 Req'd Qty: 8.00		; ; ;	Cust Item ID: Customer:			- 1			
Approvals:	Process Plan QC:	n:	Date: 169-01	Tooling: SPC (Y/N):	Date:		R	un Star Stop			
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Tool ID To	ol # Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	Revi	ision Nbr									
D4103	Α .										_
100 		Cut blanks as per folio  Memo 6.200" long		0.00	SL 16/09/23		8	\$			
110 HAAS I HAAS CNC vertical	machine #1	<b>Memo</b> Mill as per o	dwg and Folio FA937	0.00	10/09/27 10/09/28		_8_	8			
120 QC Quality Control		DEBURR  QC2- Inspect parts off m	nachine FAI/FAIB	0.00	L 10/09/27 10/09/28		_&_				

	•									
W/O:			WO	RK ORDER CHANG	ES					•
DATE	STEP	PRO	OCEDURE CHAI	NGE	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		>								
Part No		PAR #:								
	R	esolution:	Disposition	):	_ QA: N	/C Clo	sed:		Date: _	· · · · · · · · · · · · · · · · · · ·
NCR:			WORK ORDE	ER NON-CONFORMA	NCE (	NCR)				
DATE	STEP	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval
DATE		Description of NC Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section C	Chief Eng	QC Inspector	
					, l					
									·	
					-					
								-		
									) +· ý	

Work Orde Tuesday, Septemb											Page 2
Revision ID:	D4103-1 Step / Handle			Accept				Setup	Start Stop		
Start Date: Required Date: Reference:	9/7/2010 10/13/2010	Start Qty: 8.00 Req'd Qty: 8.00	1   1   1   1   1   1   1   1   1   1		Cust Item ID Customer:	<b>):</b>					
Approvals:	Process Pla		Date:	Tooling: SPC (Y/N):	Dat		-	Run	Start Stop		
Sequence ID/ Work Center ID  130 QC Quality Control	,	Operation Description QC8- Inspect parts - secon	d check	Set Up/ Run Hours 0.00	Tool ID	Tool # Plan Cod		ot Re Qt		Reject Number	Insp. Stamp
140 HandFinish		Chemical Conversion Coa	t per QSI005 4.1	0.00 FL /C	)-9 <b>-2</b> 9.		8	<b>&amp;</b>	<i>,</i>		

150

Hand Finishing

Quality Control

QC3- Inspect Part Finish

Memo

0.00 => M 10/09/29 8 A

Dart Ae	rospace	e Ltd							, "
W/O:			WC	RK ORDER CHANGE	S				4
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	. <u> </u>
	R	esolution:	Disposition	າ:	QA: N/C C	losed:		Date: _	
NCR:		V	VORK ORDE	ER NON-CONFORMA	NCE (NC	₹)			
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	n B   <b>Sign</b> 6	0	cation	Approval	Approval
		Section A	Chief Eng	Chief Eng	Date		on C	Chief Eng	QC Inspector
				·					

#### Work Order ID 61814

Tuesday, September 07, 2010 12:43:57 PM



Page 3

Item ID:

D4103-1

Accept

Date:

Tool # Plan

Code

Setup Start

Stop



**Revision ID:** 

Item Name:

Step / Handle

**Start Date:** 

9/7/2010

Start Qty: 8.00

Req'd Qty: 8.00 **Required Date:** 10/13/2010



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

QC:

Process Plan:

Date:\_\_\_\_\_

Tooling: Date:

SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Tool ID

Run Start



Accept

Qty

Reject Reject

Stop

Insp. Stamp Number

Sequence ID/ Work Center ID

160

Packaging Packaging

Operation Description

Identify as per dwg & Stock Location:

Memo

0.00

0.00

Qty

170

QC Quality Control

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

W/O:			W	ORK ORDER CHANGE	S				Q.		
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						···					
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	<b>A</b> :	Date: _			
	Re	esolution:	Disposition	on:	QA: N/C CI	osed:	sed: Date:				
NCR:			WORK ORD	ER NON-CONFORMAN	ICE (NCF	R)					
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval		
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti		Chief Eng	QC Inspector		

#### Picklist Print

Tuesday, September 07, 2010 12:44:01 PM

Work Order ID: 61814

Parent Item: D4

D4103-1

Parent Item Name: Step / Handle



**Start Date:** 9/7/2010

**Required Date:** 10/13/2010

Page 1

Start Qty: 8.00

Required Qty: 8.00

**Comments:** 

IPP REV: A NEW ISSUE 10-07-01 JLM VERIFIED BY:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M6061T6B2.000X03.50		Purchased	No		100	f	17.6427	0.52	4.378947	7 .		



6061-T6 Bar 2.00 x 3.50

 Location
 Loc Oty
 Loc Code

 MAT09
 17.6427

 112764
 17.6427

4.4

W/O:			WORK ORDER (	ER CHANGES						
DATE	STEP	Ī	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector		
			•							
			N. Committee of the Com							
• •										
Part No		PAR #:	Fault Category:	NCR: Ye	es No <b>DQ</b>	<b>A</b> :	Date: _			
	Res	olution:	Disposition:	QA: N/C	Closed:		Date: _			

NCR:			WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	Approval	Ammunia					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector					
		·											
NOTE: D	ate & initial a	all entries				<u></u>	L	<u> </u>					

DART AEROSPACE LTD	Work Order:	61814
Description: Step /Handle	Part Number:	D4103-1
Inspection Dwg: j)4/03 Rev: A		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
2.93	=-036	2.930	\		Vern	ML-7
.37	±.038	-371			11	
.83	±.030	828	,		ĮĆ.	((
851.1	÷. D/h	8.561			. 11	/(
.06 X45°	1.030 X = 12°	D67× 45°			1(	(,
.26	±-036	270			<i>(</i> (	(( '
.33	± 030	-335			٠,	1(
R.ble	± 030	R. 060			Radius geze	REF
1.78	± 03b	1.784			Vern	ML-7
.45	± 636	.445	1	<u>.</u>	11	((
.45	±.030	.335			1,	(,
.75	+.000 -:030	740			i,	
.75 1.66	±.030	1.650			11	((
.80	±-030	.770			710	"(
1.07	±.030	1.070			H-gage	31006
3.85	= 630	3.849			Vern	11-7
.03 × 45°	+ 630 X=1/2°	.040X450		·	VI	- 11
.31	+ 036	3/0	_		7 1	. 1
.28	± 036	.280			11	1 (
. 030 Deep		.030			1.	(\
6.00	± 636	6.000			. )(	
R.27	±-030	R.270			Radius gege	REF
.56	± 030	552			Vern	ML-7

ļ	Measured by:	and	Audited by:		Prototype Approval:	N/A
	` Date:	10/09/27	Date: 10/09	28	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	

DART AEROSPACE LTD	Work Order:	61814
Description: Step/Handle	Part Number:	D4103-1
Inspection Dwg: DUID3 Rev: A		Page 1 of 3


### FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

	1				
Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
±.030	1.747	/		H-gage	31006
± 030	2.498			Mern	ML-7
006	8.440			l ı	
+.006	Ø.270			1.	· (
	.953			H-gage	31006
	254			the ro	31006 ML-8 ML-7
	.245			Vern	Mr-7
±.030	2.248			, (	ι
±.036	1.000			1 (	
- 036	.197			t (	
± 030	.980	-		11	1(
±. 030	.318				, \
±.080	1.248			((	
= 030	R. 190			Redis gage	REF
				10	
					· · · · · · · · · · · · · · · · · · ·
	± 030 ± 036 • 007 + 006 + 036 ± 036 ± 036 ± 036 ± 036 ± 036 ± 036 ± 030 ± 030 ± 030 ± 030	Tolerance Dimension  +.030	Tolerance Dimension Accept  + 030	Tolerance    Dimension   Accept   Reject	Tolerance  Dimension  Accept Reject Inspection  1.747  1.7

Measured by:	and	Audited by:	STO	Prototype Approval:	N/A
Date:	10/01/27	Date:	10/09/28	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	




	. Johann												
W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	· · · · · · · · · · · · · · · · · · ·				
Resolution:		Disposition: Q			QA: N/C Closed: Date:								
NCR:		\	WORK ORDI	ER NON-CONFORMA	NCE (NC	R)							
DATE	CTED	Description of NC		on B	Verific	cation	Approval	Approval					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti	Section C	Chief Eng	QC Inspector				
									•				
1													
				•									
		·											
			1 1						1				


8 W/6 41814 D D 0.06 x45° CAMFER-0.26 Ø0.560 2 PL 1.66 REF 0.25 TYP 6.00 Ø0.438 0.80 DEEP, 2PL R0.27 TYP 2.93 REF 10000 0.31 TYP С R0.06 TYP 1.78 0.80 话户 2.50 0.37 -0.03 x 45\* CHAMFER 0.45 0.83 REF 0.75+0.00 В -0.06 x45° CAMFER VIEW B-B D3-1 SCALE 0.5X VIEW C-C SCALE 0.5X SECTION A-A D6-1 DESIGN DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA Α DRAWN DRAWING NO. D4103 CHECKED REV. A MFG. APPR. SHEET 2 OF 3 APPROVED TITLE SCALE STEP/HANDLE DE APPR. NTS COPYRIGHT @ 2010 BY DART AEROSPACE LTD DATE 10.05.17 3

W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
							1						
**************************************								·					
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	lo DQA:	Date: _						
Resolution: Disposition:			QA: N/C Closed: Date:										
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)			,					
DATE	STEP	Description of NC	n of NC Corrective Action Section			Verification	Approval	Approval					
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector					
		,											
			·	· · · · · · · · · · · · · · · · · · ·									
		,											
				•									


Wo 61814



VIEW D-D C8-2 SCALE 0.5X



**VIEW E-E** D7-1



VIEW F-F C1-1

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA					
DRAWN	RF,						
CHECKED	#	DRAWING NO.	REV. A				
MFG. APPR.	4/	D4103	SHEET 3 OF 3				
APPROVED	4	TITLE	SCALE				
DE APPR.		STEP/HANDLE	NTS				
DATE 10.0	5.17	COPYRIGHT © 2010 BY DART A THIS DOCUMENT IS PRIVATE AND COMPIDENTIAL AND IS SUPPLIES NOT TO BE USED FOR ANY PURPOSE OR COMED OR COMMUNIC MENTERS OF THE PRIVATE OF THE PRIV	ON THE EXPRESS CONDITION THAT IT IS ATED TO ANY OTHER PERSON WITHOUT				

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		. *			· · ·							
							**************************************		•			
				· • • • • • • • • • • • • • • • • • • •								
Part No		PAR #:	Fault Ca	tegory:	NC	R: Yes	No <b>DQ</b>	A:	_ Date: _			
Resolution:			Disposition: Q			QA: N/C Closed: Date				·		
NCR:			WORK OR	DER NON-CONFO	PRMANCE	(NCR	1)	,		,		
DATE	STEP	Description of NC	1-22-1	Corrective Action Section B			Verification		Approval	Approval		
		Section A	Initial Chief Eng	Action Descrip Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector		
									}			
			·									
					•							
•		,								¥		
		Į.										